



UNITEDTEK CORPORATION

Email: utk@seed.net.tw

| <u>UT NO.</u> | <u>OEM NO.</u> | <u>MAKE</u> | <u>DESCRIPTION</u> | <u>PART</u> | <u>NOTE</u> |
|---------------|----------------|-------------|----------------------|-------------------|-------------|
| UTC05-2943 | 0K011-32-260A | KIA | SPORTAGE 95-02 | CENTER LINK | OUT RH |
| UTC05-2942 | 2541-32-250A | MAZDA | B1600 72-76 | CENTER LINK | |
| UTC05-4556 | MB166276 | MITSUBISHI | PICKUP 87-89 (MIGHTY | CENTER LINK 87-89 | (2WD) |
| UTC07-2915 | MB166769 | MITSUBISHI | MIGHTY MAX 83-96 | CENTER LINK | |
| UTC05-4557 | MB166987 | MITSUBISHI | PICKUP 87-96 (MIGHTY | CENTER LINK | (4WD) |
| UTC05-4560 | MB564850 | MITSUBISHI | PICKUP 87-96 (MIGHTY | CENTER LINK 90-96 | (2WD) |
| UTC05-2941 | 48560-43W00 | NISSAN | 720 PICKUP 80-83 | CENTER LINK | |
| UTC05-2939 | 48560-B5000 | NISSAN | 521 PICKUP 69-72 | CENTER LINK | |
| UTC05-2939 | 48560-B5000 | NISSAN | 620 PICKUP 72-79 | CENTER LINK | |
| UTC05-2940 | 48560-W5725 | NISSAN | 210 79-82 | CENTER LINK | |
| UTC05-2940 | 48560-W5725 | NISSAN | 510 78-81 | CENTER LINK | |
| UTC05-4119 | 45451-34010 | TOYOTA | T100 PICKUP 93-98 | CENTER LINK | (4WD) |